




KC #7316

Two Black Powder Coat
Light Brackets for
Jeep JK Wrangler 07-10



Remove T-40 Torx bolts from the upper half of the factory windshield hinge. Position light mount over hinge. Align holes and secure mount using the factory bolts.



***Periodically check bolts
for tightness.***